

## HC18M121E2-SOP14 引脚图

<b>VDD</b>	1	14	<b>GND</b>
<b>OSCI/AN14/PORTB6</b>	2	13	<b>PORTA2/AN2/PCK/V<sub>REF</sub>/TM1PWM</b>
<b>OSCO/AN15/PORTB7</b>	3	12	<b>PORTA3/AN3</b>
<b>T2CKI/TM2PWM/AN7/PORTA7</b>	4	11	<b>PORTA1/AN1/PGD/TM2PWM</b>
<b>VPP/PORTB5</b>	5	10	<b>PORTA0/AN0/PGC/TM1PWM</b>
<b>TM2PWM/AN11/PORTB3</b>	6	9	<b>PORTB0/AN8/INT0/TM1PWM/T1CKI</b>
<b>T0CKI/TM1PWM/AN10/PORTB2</b>	7	8	<b>PORTB1/AN9/INT1/TM2PWM</b>

HC18M121E2-SOP14-转接板接线图

